

To: Faulk, Libby[Faulk.Libby@epa.gov]
Cc: McClain-Vanderpool, Lisa[Mcclain-Vanderpool.Lisa@epa.gov]; Davis, Tim[Davis.Tim@epa.gov]; Stevenson, Peter[Stevenson.Peter@epa.gov]
From: Smith, Paula
Sent: Mon 8/10/2015 5:26:23 AM
Subject: Re: Catch basins operating

Great shots. Thanks!

Sent from my iPhone

On Aug 9, 2015, at 11:21 PM, Faulk, Libby <Faulk.Libby@epa.gov> wrote:

Libby Faulk, Program Manager
Public Affairs and Community Involvement Program
U.S. EPA, Region 8
303-312-6083

Begin forwarded message:

From: "Daniel Bender" <Dan.Bender@co.laplata.co.us>
To: "Susan Hakanson" <Susan.Hakanson@co.laplata.co.us>, "Sarah Jacobson" <Sarah.Jacobson@co.laplata.co.us>, "Joanne Spina" <Joanne.Spina@co.laplata.co.us>, "Joe Kerby" <Joe.Kerby@co.laplata.co.us>, "Sean Smith" <Sean.Smith@co.laplata.co.us>, "Frank Sandoval" <Frank.Sandoval@co.laplata.co.us>, "Edward Aber" <Edward.Aber@co.laplata.co.us>, "Todd Hitti" <Todd.Hitti@co.laplata.co.us>, "Butch Knowlton" <Butch.Knowlton@co.laplata.co.us>, "Tom McNamara" <tommymoto@gmail.com>, "Faulk, Libby" <Faulk.Libby@epa.gov>
Subject: Catch basins operating

Attached are catch basins just above Cement Creek. I sent photos to some of you Saturday showing them in final stages of readiness. There are additional basins at the mine portal. Also attached is Cement Creek running thru a culvert at the intersection of SJC Rds 110 & 10. Significantly clearer than photos I took at the same location Saturday Dan Bender, LPCSO

<IMG_0384.JPG>

<IMG_0373.JPG>

<IMG_0368.JPG>

Sent from my iPhone